

Non-Towered Airport Operations - 'WINGS' Safety Program (P48)

Arizona has over 85 airports with NO control tower. Learn the correct procedures for operating at a non-towered airport.

Directions: Flying: P48 is on the edge of the Luke SATR North Area and has a 40/30 ft shelf 3 nm south of the airport, and inside the 30nm mode C PHX class B. If not familiar with P48, its traffic patterns and procedures, it is recommended that you drive to the event. There are NO paved runways. Driving: West on Carefree HWY (Az HWY 74) from I-17 to Lake Pleasant Rd, turn South on lake pleasant Rd just after the windsock. *Seminar in Only Bldg on Airport - Look for Signs*

A message from the National FAASafetyTeam Manager

Invite a fellow pilot to the next WINGS Safety Seminar in your area
Sign up for the FAA's safety services at www.FAASafety.gov!

Event Details

Sat, Feb 9, 2013 - 10:00 am

Pleasant Valley Airport

8700 W. Carefree HWY

Peoria, AZ 85383



Contact: FRED L. GIBBS

(928) 266-0112

fredgibbs@npgcable.com

Select #: WP0747972

Lead Representative FRED L. GIBBS

The FAA Safety Team (FAASafetyTeam) is committed to providing equal access to this meeting/event for all participants. If you need alternative formats or services because of a disability, please communicate your request as soon as possible with the person in the "Contact Information" area of the meeting/event notice. Note that two weeks is usually required to arrange services.